

Updated Recommendations for COVID-19 PPE

For persons under investigation or positive for COVID-19:

- Standard, contact, and airborne precautions with eye protection are recommended.
- Surgical masks with face shields may be acceptable for lower-risk patients if N95 respirators or PAPRs/CAPRs are not available.
- N95 respirators or PAPRs/CAPRs are mandatory for aerosol-generating procedures.

DONNING SEQUENCE



1. **Perform hand hygiene.***
2. Full coverage gown fastened at the neck & waist
3. Mask or respirator as recommended
4. Goggles or face shield to cover face & eyes
5. Gloves extended to cover wrist of isolation gown

*Wash for ≥ 20 seconds with soap and water or use an alcohol-based sanitizer.

DOFFING SEQUENCE



1. Remove gloves to avoid contamination.
2. Unfasten gown at back. Pull gown away from body, and turn gown inside out in a bundle to dispose in waste container.
3. **Perform hand hygiene.***
4. Goggles and face shields should be removed using straps to avoid contamination.
5. DO NOT touch front of mask or respirator; remove by grasping elastics in the back.
6. **Perform hand hygiene.***